

2008 RESNET Building Performance Conference

Session 4 Meeting the RESNET Provider Quality Assurance Monitoring Challenge

Prepared by: EAM Associates, Inc.

Wall, New Jersey February 19, 2008





What is Quality Assurance ("QA")?

- QA is defined as: "a program for the systematic monitoring and evaluation of the various aspects of a project, service, or facility to ensure that standards of quality are being met".
- EAM views QA as a tool to determine or confirm our work products and services meet or exceed our customer and industry expectations.
- EAM has adopted QA as a process-driven approach with specific steps to attain our goals.
- Creating a Process, and sticking with it.





What EAM Does

- REM Analysis review: It doesn't have to be perfect, just close to it – 10% miniumim
- Field Review: 1% is the minimum
- Compare results side by side also take into account what is or is not missing from reports
- Discuss findings Good and Bad Honesty is the best policy
- Keep records you may want or need them for future reference



Rater Name:		_ Track	ing Number: _					
Date	e Reviewd:		I	Reviewed By: _				
					Rebate V	Vork-Sheet	REM ARE	A vs PLANS
	Quality Co	ntrol Item	Correct	Incorrect	Correct	Incorrect	Correct	Incorrect
1	Electronic File in Proper	Location						
2	Site Location							
3	Utilities							
4	Address							
5	Energy Rating Informat	ion			Rebatable	e Square Ftg		
6	Area and Volume							
7	Foundation							
8	Slab							
9	Frame Floor				Notes & Doc	umentation		
10	Above Grade Walls	Insulation						
11		Color						
12	Ceilings	Insulation						
13		Radiant Barrier						
14		Color			ARIN	lumbers		
15	Windows:	Values						
16		Orientation						
17		Wall Assignment						
18	Doors				Ca	pacity		
19	Heating Equipment:	Size						
20	0.11	Efficiency			· · · · · · · · · · · · · · · · · · ·			
21	Cooling Equipment:	Size			A 167 170			
22		Efficiency						
23	Hot Water Heater:	Size			· 2.			
24		Efficiency						
25	Duct Properties:	Location						
26		Insulation						
27		Distribution			Lighting &	& Appliances		
28		Leakage						
29	Infiltration				Mecha	nical Vent.		
30	Mechanical Ventilation							
31	Ventilation Strategy for	Cooling						


Comments:

February 19, 2008

© 2008 EAM Associates, Inc.



EAM 2006 RATER PRODUCTIVITY TRACKING REPORT






Tracking Number: Date: Project Name: Weather Condition: Quality Control Item Q/A Rater 1 House ready for inspection	F	Rater Name:		Inspection Type:							
Quality Control Item Q/A Rater I House ready for inspection	1	Tracking Number:		Date:							
Learning control room Critical Section 2 Mechanicals installed and numbers noted	F	Project Name:		Weather Condition:							
2 Mechanicals installed and numbers noted Image: State Stat		Quality	Control Item	Q/A	Rater						
3 Thermostats noted correctly Image: Second	1	House ready for inspection									
4 Biower Door Numbers Image: Constant of the section of the secti	2	Mechanicals installed and n	umbers noted								
5 Duct Blaster Numbers	3	Thermostats noted correctly									
6 Foundation Insulation Insulation 7 Type of Foundation Insulation (Biown) 8 Ceiling Insulation (Biown) Insulation (Biown) 9 Floor over uncndthd space (crawl or basement) R-Value Insulation fully supported to subfir 10 Insulation fully supported to subfir Insulation fully supported to subfir 11 Supply/Return boxes to Drywall (to uncond.space) Insulation fully supported to space) 12 Recessed lighting to Drywall (to unconditioned space) Insulated 13 Access/Door to Attic: Weatherstripped 14 Insulated Insulated 15 Above Grade Walls: Exterior Color 16 Roof: Exterior Color 17 Exterior Penetrations Sealed Insulated 19 Structural Options verified Insulated 20 Pass or Fail Insulated 21 Review of Completed Paperwork Insulated 22 Noted Site Problems Clearly: Insulated 23 Discussed Issues on Site: Insulated	4	Blower Door Numbers									
7 Type of Foundation Image: Section of the sectin of the section of the section of the section	5	Duct Blaster Numbers									
8 Celling Insulation (Blown) Image: Construct of the system of the	6	Foundation Insulation									
9 Floor over unendthd space (crawl or basement) R-Value Image: Supply Return boxes to Drywall (to uncond.space) 10 Insulation fully supported to subfir Image: Supply Return boxes to Drywall (to uncond.space) 12 Recessed lighting to Drywall (to uncond.space) Image: Supply Return boxes to Drywall (to uncond.space) 13 Access/Door to Attic: Weatherstripped 14 Insulated 15 Above Grade Walls: Exterior Color 16 Roof: Exterior Color 17 Exterior Penetrations Sealed Image: Supply Return of Supply Return	7	Type of Foundation									
10 Insulation fully supported to subfir 11 Supply/Return boxes to Drywall (to uncond.space) 12 Recessed lighting to Drywall (to uncond.tioned space) 13 Access/Door to Attic: 14 Insulated 15 Above Grade Walls: 16 Roof: 17 Exterior Color 18 Orientation 19 Structural Options verified 20 Pass or Fail 21 Review of Completed Paperwork 22 Noted Site Problems Clearly: 23 Discussed Issues on Site:	8	Ceiling Insulation (Blown)									
Supply/Return boxes to Drywall (to uncond.space)	9	Floor over uncndtnd space (crawl or basement) R-Value								
12 Recessed lighting to Drywall (to unconditioned space)	10	Insulat	tion fully supported to subfir								
Access/Door to Attic: Weatherstripped 14 Insulated 15 Above Grade Walls: Exterior Color 16 Roof: Exterior Color 17 Exterior Penetrations Sealed	11	Supply/Return boxes to Dry	wall (to uncond.space)								
Insulated Insulated Insulated Insulated Image: Stream of the stream of	12	Recessed lighting to Drywal	I (to unconditioned space)								
15 Above Grade Walls: Exterior Color 16 Roof: Exterior Color 17 Exterior Penetrations Sealed	13	Access/Door to Attic:	Weatherstripped								
16 Roof: Exterior Color 17 Exterior Penetrations Sealed 18 Orientation 19 Structural Options verified 20 Pass or Fail 21 Review of Completed Paperwork 22 Noted Site Problems Clearly: 23 Discussed Issues on Site:	14		Insulated								
7 Exterior Penetrations Sealed 18 Orientation 19 Structural Options verified 20 Pass or Fail 21 Review of Completed Paperwork 22 Noted Site Problems Clearly: 23 Discussed Issues on Site:	15	Above Grade Walls:	Exterior Color								
8 Orientation 19 Structural Options verified 20 Pass or Fail 21 Review of Completed Paperwork 22 Noted Site Problems Clearly: 23 Discussed Issues on Site:	16	Roof:	Exterior Color								
19 Structural Options verified 20 Pass or Fail 21 Review of Completed Paperwork 22 Noted Site Problems Clearly: 23 Discussed Issues on Site:	17	Exterior Penetrations Sealed	d								
20 Pass or Fall 21 Review of Completed Paperwork 22 Noted Site Problems Clearly: 23 Discussed Issues on Site:	18	Orientation									
20 Pass or hall	19	Structural Options verified									
22 Noted Site Problems Clearly: 23 Discussed Issues on Site:	20	Pass or Fail		·····	1 A 10.0						
23 Discussed Issues on Site:	21	Review of Completed Paper	work								
	22	Noted Site Problems Clearly	/:								
24 Comments & Notes:	23	Discussed Issues on Site:									
	24	Comments & Notes:									

Q/A Signature:

Date Reviewed with Rater:





EAM Associates REMRate Quality Assurance Documentation 2006

Rating Number/ID #	Builder Name	House Address	City	State	Zip	Rater Name	Date - Building File Reviewed by		QA Building File Review Date/Findings
Rating Numbernu #	Buider Name	House Address	ony	Child					
0090-42-V-73CountryClub	Toli Brothers, inc.	73 Country Club Drive	Monroe	NJ	08831	Don Gissubel	1/20/06	Y - 1/24/06	HWH efficiency incorrect
M090-357-V-4Opal	Farmingdale Woods, LLC	4 Opal Court	Jackson	NJ	08527	Don Gissubel	1/21/06	Y - 1/24/06	Color of Walls and Cellings Incorrect, SEER of A/C 13 instead of 13.5
M090-103-V-190Blackberry	Kalian/Spectrum Monroe, LLC	190 Blackberry Drive	Monroe	NJ	08831	Don Gissubel	1/22/06	Y - 1/31/06	Radiant Barrier entered when none
M090-103-V-188Blackberry	Kalian/Spectrum Monroe, LLC	188 Blackberry Drive	Monroe	NJ	08831	Don Gissubel	1/23/06	Y - 1/31/06	Good
D090-360-V-3Meredith	Toll Brothers, Inc.	3 Meredith Court	Freehold	NJ	08827	Don Gissubel	1/24/06	Y - 2/3/06	Ceiling color incorrect - Good otherwise
D090-571-V-1Meadowview	Paramount Homes	1 Meadow Run Court	Jackson	NJ	08527	Don Gissubel	1/25/06	Y - 2/7/06	Ceiling joist spacing incorrect - Good otherwise
D090-622-V-27Wilson	Lennar Corporation	27 Wilson Boulevard	Jackson	NJ	08527	Don Gissubel	1/26/06	Y - 2/7/06	Foundation type listed incorrectly
S04-107-JNG-V-18Streambank	Lennar Corporation	18 Streambank Drive	Howell	NJ	07731	Don Gissubel	1/27/06	Y - 2/8/06	Wall & ceiling color incorrect, duct distribution incorrect.
S04-107-JNG-V-16Streambank	Lerina: Corporation	10 Secandaria Silva	1 CHOIL						
090-391-V-57Crestview	Orleans Homebuilders	57 Crestview Drive	Clinton	NJ	08809	Don Gissubel	1/28/06	Y - 3/9/06	Good
090-391-V-58Crestview	Orieans Homebuilders	58 Crestview Drive	Clinton	NJ	08809	Don Gissubel	1/29/06	Y - 3/9/06	Doors not exact - Good
D090-714-V-18Keswick	M&M at Monroe Woods, LLC	18 Keswick Circle	Monroe	NJ	08831	Don Gissubel	1/30/06	Y - 3/15/06	HWH location incorrect - otherwise Good
M090-71-V-734S.Mehar	Arya Properties	734 South Mehar Court	Toms River	.NJ	08753	Don Gissubel	1/31/06	Y - 3/21/06	Electronic file in wrong location, but REM is Good
S04-181-JNG-V-195Brigantine	Lennar Corporation	195 Brigantine Boulevard	Waretown	NJ	08758	Don Gissube	2/1/06	Y - 3/31/06	Electronic file in wrong location, Wall color incorrect, mech. Vent. not entered.
S04-181-JNG-V-187Brigantine	Lennar Corporation	187 Brigantine Boulevard		NJ	08758	Don Gissube	2/2/06	Y - 3/31/06	Mechanical Vent. not entered
S04-181-JNG-V-181Brigantine	Lennar Corporation	181 Brigantine Boulevard	Waretown	NJ	08758	Don Gissube	2/3/06	Y - 3/31/06	Mechanical Vent. not entered
109/120	Toll Brothers, Inc Morris Hunt		Flanders	NJ	07836	Don Gissube	2/4/06	Y - 3/31/06	Ceiling Color incorrect, HWH ef incorrect,
D090-495-V-13Sovereign		1 Sycamore Road	Chatham	NJ	07928	Don Gissube	-	Y - 4/4/06	Frame floor incorrect, Ceiling color incorrect, Duct Distribution incorrect
S04-113-JPS-V-1Sycamore	Heritage Manor Homes Toll Brothers, Inc Regency at	135 Country Club Drive	Monroe	NJ	08831	Don Gissube		Y - 4/4/06	Color of Walls and Ceilings Incorrect, Framing spacing of ceiling incorrect.
D090-42-V-135CountryClub D090-194-V-10CrestFruit	Paramount Homes	10 Crest Fruit Court	Manalapan	NJ	07726			Y - 4/17/06	Size of HWH incorrect - no effect on rating - good

1



EAM Associates RESNET Quality Assurance Documentation 2006

Rating Number/ID #	Builder Name	House Address	City	State	Zip	Rater Name		QA Building File Reviewed? Y/N	QA Building File Review Date/Findings	Date - House Field Tested by Rater	QA Field Reviewed? Y/N	QA Field Review Date/Findings
090-42-V-73CountryClub	Toll Brothers, Inc.	73 Country Club Drive	Monroe	NJ	08831	Don Gissube	1/20/06	Y - 1/24/08	HWH efficiency incorrect			
1090-357-V-4Opal	Farmingdale Woods, LLC	4 Opel Court	Jackson	NJ	08527	Don Gissube	1/21/06	Y - 1/24/08	Color of Walls and Ceilings Incorrect, SEER of A/C 13 instead of 13.5			
1090-103-V-190Blackberry	Kallan/Spectrum Monroe, LLC	190 Blackberry Drive	Monroe	NJ	08831	Don Gissube	1/22/06	Y + 1/31/06	Radiant Barrier entered when none			
1090-103-V-186Blackberry	Kallan/Spectrum Monroe, LLC	188 Blackberry Drive	Monroe	NJ	08831	Don Gissube	1/23/06	Y - 1/31/06	Good			
090-360-V-3Meredith	Toli Brothers, Inc.	3 Meredith Court	Freehold	NJ	05827	Don Gissube	1/24/08	Y - 2/3/06	Ceiling color incorrect - Good otherwise			
								1922032-1	Ceiling joist spacing incorrect - Good			
000-571-V-1Meadowview	Paramount Homes	1 Meadow Run Court	Jackson	NJ	08527	Don Gissube	1/25/06	Y - 2/7/08	othenwise		-	
0090-622-V-27Wilson	Lennar Corporation	27 Wilson Boulevard	Jackson	NJ	08527	Don Gissube	1/28/08	Y - 2/7/08	Foundation type listed incorrectly			
04-107-JNG-V-18Streambank	Lennar Corporation	18 Streambank Drive	Howell	NJ	07731	Don Gissube	1/27/06	Y - 2/8/05	Wall & ceiling color incorrect, duct distribution incorrect.			
90-391-V-57Crestview	Orleans Homebuilders	57 Crestview Drive	Clinton	NJ	08809	Don Gissube	1/28/06	Y - 3/9/06	Good			
90-391-V-58Crestview	Orleans Homebuilders	58 Crestview Drive	Clinton	NJ	08809	Don Gissube	1/29/06	Y - 3/9/08	Doors not exact - Good		-	
0090-714-V-18Keswick	M&M at Monroe Woods, LLC	18 Keswick Circle	Monroe	NJ	05831	Don Gissube	1/30/08	Y - 3/15/08	HWH location incorrect - otherwise Good		-	
M090-71-V-7345 Mehar	Arya Properties	734 South Mehar Court	Toms River	LN.	05753	Don Gissube	1/31/08	Y - 3/21/06	Electronic file in wrong location, but REM is Good			
804-181-JNG-V-195Brigantine	Lennar Corporation	195 Brigantine Boulevard	Waretown	NJ	08758	Don Gissube	2/1/06	Y - 3/31/08	Electronic file in wrong location, Wall color incorrect, mech. Vent. not entered.			
804-181-JNG-V-187Brigantine	Lennar Corporation	187 Brigantine Boulevard	Waretown	NJ	08758	Don Gissube	2/2/06	Y - 3/31/08	Mechanical Vent. not entered			
04-181-JNG-V-181Brigantine	Lennar Corporation	181 Brigantine Boulevard	Wanetown	NJ	08758	Don Gissube	2/3/06	Y - 3/31/06	Mechanical Vent. not entered		_	
ANA-101-2NO-Y-101Digantine	Central Components	tor bigmine boarding	The stores	110	00,00			11 × V 1	Ceiling Color incorrect, HWH ef			
D090-495-V-138overeign	Toll Brothers, Inc Morris Hunt	13 Sovereign Dr.	Flanders	NJ	07836	Don Gissube	2/4/06	Y-3/31/08	incorrect/			
504-113-JPS-V-18ycamore	Heritage Manor Homes	1 Sycamore Road	Chatham	NJ	07928	Don Gissube	2/5/08	Y - 4/4/06	Frame floor incorrect, Ceiling color incorrect, Duct Distribution incorrect			
Source and the presented		, of care of the second							Color of Walls and Cellings Incorrect			
D090-42-V-135CountryClub	Toll Brothers, Inc Regency at Monroe	135 Country Club Drive	Monroe	NJ	08831	Don Gissub	2/6/06	Y - 4/4/08	Framing spacing of ceiling incorrect.			
D090-194-V-10CrestFnait	Paramount Homes	10 Crest Fruit Court	Manalapan	NJ	07726	Don Gissub	2/7/06	Y - 4/17/08	Size of HWH incorrect - no effect on rating - good		-	
0090-194-V-15CrestFruit	Paramount Homes	15 Crest Fruit Court	Manalapan	NJ	07726	Don Gissub	2/8/06	Y - 4/17/06	Color of ceilings incorrect - good			
		-						Y - 4/17/08	Color of cellings incorrect, Duct			
0090-194-V-15Staymen	Peramount Homes	15 Staymen Court	Manalapan	NJ	07728	Don Gissub	2/9/05	1.14/17/28	leakage missing 1 system testing.			
D090-194-V-78taymen	Paramount Homes	7 Staymen Court	Manalapan	NJ	07726	Don Gissub	2/10/06	Y-4/17/08	Size of HWH incorrect - no effect on rating - good	-	-	
	Cedar Village at Ocean, LLC	20 Boxwood Drive	Ocean	NJ		Don Gissub	2/11/08	Y - 4/18/08	Good			

1/29/2008



Why QA is Important

QA demonstrates credibility - that the necessary precautions have been taken to offer "assurance" that the product or service is within or above nationally accepted standards.



SUMMARY

- Establish QA objectives & processes to deliver desired results for both your company and RESNET
- Implement the QA Process developed and make your raters aware of it
- Make sure you are (at a minimum) meeting the Industry standard for QA – RESNET

 Apply actions remediation if the QA results indicate it is needed.



Questions and Answers

Thank You!

Ann Marie Apgar Technical Services Manager aapgar@eamenergy.com

> EAM Associates, Inc. Wall, New Jersey 07719

732-556-9190 voice 732-556-9195 fax



